

CERTIFICATE OF COMPLIANCE

Certificate Number 20190828-R13081
Report Reference R13081-20190822
Issue Date 2019-AUGUST-28

Issued to: HILTI CONSTRUCTION CHEMICALS, DIV OF HILTI INC
7250 Dallas Pky, Legacy Tower Suite 1000
Plano TX 75024

**This certificate confirms that
representative samples of**

FORMING MATERIALS
Firestop Top Track Seal (TTS) CFS-TTS MD P Flute Plugs
and CFS-TTS MD C Flute Covers for use in joint systems.

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

ANSI/UL 2079, "Tests for Fire Resistance of Building Joint
Systems"


Standard(s) for Safety: ULC-S115, Standard Method of Fire Tests of Firestop
Systems.

Additional Information: See the UL Online Certifications Directory at
<https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations>

